

ACKNOWLEDGMENT OF COMPLETION REPORT

FOR

BNSF PANHANDLE DERAILMENT WEST OF INTERSECTION U.S. HIGHWAY 60 AND FARM-TO-MARKET 293E SPUR PANHANDLE, CARSON COUNTY, TEXAS

Prepared for

U.S. Environmental Protection Agency
Will LaBombard, Project Officer
1445 Ross Avenue
Dallas, Texas 75202

Contract No. EP-W-06-042
Technical Direction Document No. 1/WESTON-042-16-023
WESTON WON 20406.012.001.1019.01
NRC No. 1151859
FPN ID N/A
CERCLIS ID N/A
EPA OSC William Rhotenberry
START-3 PTL José Ojeda

Submitted by

Weston Solutions, Inc.
Cecilia H. Shappee, P.E., Program Manager
5599 San Felipe, Suite 700
Houston, Texas 77056
(713) 985-6600

September 2016

1. INTRODUCTION

On 28 June 2016, a representative of BNSF Railway (BNSF) reported a discharge of diesel to the National Response Center (NRC) Report No. 1151859, due to a collision of two freight trains west of the intersection of U.S. Highway 60 and Farm-to-Market (FM) 293E Spur in Panhandle, Carson County, Texas. An unknown volume of diesel was reported to have impacted the ballast of the rail line. The cause of the collision is unknown as of the date of this report. On 28 June 2016, the U.S. Environmental Protection Agency (EPA) Region 6 Emergency Management Branch (EMB) activated Weston Solutions, Inc. (WESTON®), the EPA Region 6 Superfund Technical Assessment and Response Team (START-3) contractor, to conduct a Tier 2 incident response. Under direction from EPA On-scene Coordinator (OSC) William Rhotenberry and as outlined in Technical Direction Document (TDD) No. 1/WESTON-042-16-023 (Attachment I), START-3 was tasked to assess the impact of the incident and response activities; to document the incident and response activities; to analyze data that was collected; to provide technical support to EPA; to provide website updates; and to complete this Final Report.

The geographic coordinates of the train collision where the discharge originated are Latitude 35.345103° North and Longitude 101.368887° West, as determined by using a handheld Global Positioning System (GPS) based on the World Geodetic System – 1984 (WGS-84) with accuracy estimated at less than 50-foot circular probable error. A Site Location Map, Site Area Map, and Site Layout Map are included as Attachments A, B, and C, respectively.

2. BACKGROUND

On 28 June 2016 at approximately 0825 hours, two BNSF freight trains collided head-on in Panhandle, Carson County, Texas, on the main rail line known as the Southern Transcon. Initial information received by the NRC reported an unknown volume of diesel fuel spilled onto the ballast of the rail line. An incident update by BNSF and the Texas Commission on Environmental Quality (TCEQ) reported diesel from the eight locomotive engines (four engines per train) involved in the incident was burning, with no emergency evacuations or road closures initiated in the area. Three BNSF personnel were unaccounted for and presumed dead by the Texas Department of Public Safety.

Four locomotives and six railcars from the southwest bound train were derailed as a result of the collision with the northeast bound train. The six damaged railcars contained mixed commodities with no hazardous materials (HAZMAT) listed on the railroad consists. The consists listed four railcars as containing HAZMAT, but these railcars were not affected by the collision.

Four locomotives and nine railcars from the northeast bound train were derailed due to the collision with the southwest bound train. Railcars 3 and 7 were listed as containing HAZMAT on the railroad consists. Railcar 3 was listed as UN1866, resin solution (resin solution flammable), and Railcar 7 was listed as UN1325, flammable solid organic, N.O.S. (aluminum). The remaining damaged railcars were listed as mixed commodities with no HAZMAT listed on the railroad consists. The northeast bound train had three other HAZMAT rails that were unaffected.

Due to changing on-site weather conditions and variable wind direction, an evacuation of a residential area located north-northwest of the incident location was initiated.

3. SUMMARY OF ACTIONS

On 28 June 2016, the EPA Team mobilized to the Carson County Law Enforcement Center and met with Environmental Investigators for the TCEQ Amarillo Region Office. An incident briefing was conducted with the EPA Team, and then the teams proceeded to the incident location.

At the incident location, the EPA Team met with Derrick Lamkin, BNSF representative, and their environmental contractors, Center for Toxicology & Environmental Health LLC (CTEH). CTEH described the current air monitoring and sampling operations that included hourly air monitoring from 13 Fixed Real Time (FRT) locations. At each FRT location, CTEH conducted air monitoring for volatile organic compounds (VOCs), particulate matter (PM 2.5), carbon monoxide (CO), nitrous oxide (NO), and sulphur dioxide (SO₂). Hourly air sampling was conducted at 4 FRT locations for aldehydes, metals, polycyclic aromatic hydrocarbons (PAHs), and VOCs (Attachment D).

The EPA Team reviewed the available data collected by CTEH. Particulates appeared to be the primary contaminant of concern. The EPA Team proceeded to locations north of U.S. Highway 60 (directly downwind of the incident) to conduct air monitoring utilizing two DataRAM 4TM Particulate

Monitors. Particulate readings ranged from 0.03 milligrams per cubic meter (mg/m^3) to $1.60 \text{ mg}/\text{m}^3$. Prevailing winds were gusting and there were no sustained readings.

On 28 June 2016, the remains of two BNSF crew members were found. The third BNSF crew member has not been found as of the date of this report and is presumed dead.

On 29 June 2016, the EPA Team and two TCEQ Environmental Investigators accompanied CTEH personnel to conduct air monitoring concurrently at the 13 FRT monitoring locations. Average particulate readings for the locations ranged from $0.001 \text{ mg}/\text{m}^3$ to $0.007 \text{ mg}/\text{m}^3$.

BNSF began wrecking operations that consisted of accessing the impacted railcars to evaluate the condition of the cargo, and stormwater controls (absorbent boom) were placed in the ditches to prevent off-site hydrocarbon migration. Vacuum trucks were mobilized and used for diesel fuel and oil recovery.

At approximately 1300 hours on 29 June 2016, a discussion was held with BNSF regarding remaining environmental issues. BNSF representatives stated that once site safety was established and the National Transportation Safety Board (NTSB) concluded their investigation, impacted soils from discharged diesel, engine oil, and various commodities whose containers were breached and spilled, would be excavated, sampled, and sent to either a local non-hazardous landfill or to a designated hazardous waste facility per TCEQ instructions and oversight.

Based on site conditions and the briefing conducted with BNSF representatives and TCEQ personnel, OSC Rhotenberry released the EPA Team from the site on 29 June 2016.

Recovery operations continued from 30 June 2016 through 21 July 2016, which included the recovery of 13,600 gallons of diesel fuel, 550 gallons of lube oil, and 1,500 gallons of oil/water. Additional derailment materials as well as burnt rail car contents and commodities were recovered and placed into roll off boxes or stockpiled on plastic sheeting pending off-site disposal.

Recycling and disposal of the various waste streams will continue until cleanup operations are complete. Confirmation samples will be collected by BNSF representatives following waste disposal activities. The samples will be analyzed for total petroleum hydrocarbons (TPH) by Method

TX1005/1006, VOCs by Method 8260, semivolatile organic compounds (SVOCs) by Method 8270), Resource Conservation Recovery Act (RCRA) metals plus aluminum by Method 6010. If elevated concentrations of constituents of concern are reported, then additional material will be removed. A second confirmation sample will be collected at that location and analyzed, if necessary. This procedure will be repeated until analytical data confirms that all impacted material has been removed.

This Final Report was prepared as part of the requirements of TDD No. TO-0001-42-16-23 and serves as documentation of work completed. Digital photographs, the NRC Report, the site logbook, the pollution report, and TDD No. 1/WESTON-042-16-023 are provided as Attachments E, F, G, H, and I, respectively.

4. LIST OF ATTACHMENTS

- A. Site Location Map
- B. Site Area Map
- C. Site Layout Map
- D. CTEH Summary of Air Monitoring Results
- E. Digital Photographs
- F. NRC Report No. 1151859
- G. Site Logbook
- H. Pollution Report
- I. TDD No. 1/WESTON-042-16-023



☐

The EPA Task Monitor did not provide final approval of this report prior to the completion date of the work assignment. Therefore, Weston Solutions, Inc. has submitted this report absent the Task Monitor's approval.

☒

The EPA Task Monitor has provided final approval of this report. Therefore, Weston Solutions, Inc. has submitted this report with the Task Monitor's approval.

Attachment A
Site Location Map





US EPA REGION 6

ATTACHMENT A
SITE LOCATION MAP
 BNSF PANHANDLE DERAILMENT
 WEST OF INTERSECTION U.S. HIGHWAY
 60 AND FARM-TO-MARKET 293E SPUR
 PANHANDLE, CARSON COUNTY, TEXAS

DATE: AUG 2016	W.O. # 20406.012.001.1019.01	SCALE: NOT TO SCALE
-------------------	---------------------------------	------------------------

SOURCE: MICROSOFT STREETS 2010.
 NRC No.: 1151859
 TDD No.: 1/WESTON-042-16-023

Attachment B
Site Area Map



0 1000 2000

SCALE IN FEET

SOURCE: USGS 7.5 MINUTE SERIES TOPOGRAPHIC,
PANHANDLE EAST, TEXAS (2016).
NRC No.: 1151859
TDD No.: 1/WESTON-042-16-023



US EPA REGION 6

ATTACHMENT B SITE AREA MAP


BNSF PANHANDLE DERAILMENT
WEST OF INTERSECTION U.S. HIGHWAY
60 AND FARM-TO-MARKET 293E SPUR
PANHANDLE, CARSON COUNTY, TEXAS

DATE:
AUG 2016

W.O. #
20406.012.001.1019.01

SCALE:
AS SHOWN

Attachment C
Site Layout Map



0 300 600

SCALE IN FEET



US EPA REGION 6

ATTACHMENT C SITE LAYOUT MAP

BNSF PANHANDLE DERAILMENT
WEST OF INTERSECTION U.S. HIGHWAY
60 AND FARM-TO-MARKET 293E SPUR
PANHANDLE, CARSON COUNTY, TEXAS

SOURCE: GOOGLE EARTH PRO AERIAL 2016.
NRC No.: 1151859
TDD No.: 1/WESTON-042-16-023

DATE:
AUG 2016

W.O. #
20406.012.001.1019.01

SCALE:
AS SHOWN

Panhandle, TX
BNSF Train Collision/Fire

Summary of Air Monitoring Results

June 29, 2016

*Prepared by
Center for Toxicology and Environmental Health, L.L.C.*

Introduction

This report summarizes the work conducted by Center for Toxicology and Environmental Health, LLC (CTEH®) in response to a request for air monitoring support by BNSF Railway following the head-on collision and subsequent fire of locomotives and intermodal cars near Panhandle, TX. On June 28, 2016, CTEH® conducted real-time air monitoring to evaluate the potential presence of carbon monoxide (CO), nitrogen oxide (NO), particulate matter (PM_{2.5}), sulfur dioxide (SO₂), total volatile organic compounds (VOCs), and atmospheric flammability as a percentage of the lower explosive limit (LEL). This submittal summarizes real-time air monitoring data recorded on CTEH® instrumentation between the beginning of monitoring activities on June 28, 2016 17:00 to June 29, 2016 12:00.

Real-time Air Monitoring

CTEH® efforts consisted of manually-logged real-time air monitoring using handheld instrumentation. Real-time air monitoring was conducted to assess air quality in the community as well as the breathing zone of workers involved in the response. Monitoring was conducted using instruments such as the RAESystems MultiRAE Plus and MultiRAE Pro, and Gastec pumps with chemical-specific colorimetric tubes. **Table 1** summarizes the air monitoring data for manually-logged real-time readings in the community. **Table 2** summarizes the air monitoring data for manually-logged real-time readings taken to assess worker breathing zone air quality. **Attachment A** contains incident maps including site location, topography and hydrography, and manually-logged handheld real-time reading locations.

Analytical Air Sampling

CTEH® efforts consisted of deploying analytical sampling media at four locations to collect samples for the following profiles: metals, aldehydes, polynuclear aromatic hydrocarbons (PNAHs), and volatile organics using integrated sampling pumps and Minicans. Sampling for metals, aldehydes, and PNAHs are run in concurrent 12 hour periods. The hydrocarbon profile sampling period is 24 hours.

All samples will be sent to an American Industrial Hygiene-accredited analytical testing lab and results reported in future submittals as they become available.

Table 1: Manually-Logged Real-Time Air Monitoring Summary: Community Breathing Zone
June 28, 2016 17:00 to June 29, 2016 12:00

Analyte	Count of Readings	Count of Detects	Detection Range
CO (ppm)	82	0	< 1 ppm
LEL (%)	3	0	< 1 %
NO (ppm)	16	0	< 0.1 ppm
PM2.5 (mg/m3)	83	83	0.001 - 2.530 mg/m3
SO2 (ppm)	29	0	< 0.1 ppm
VOC (ppm)	83	0	< 0.1 ppm

¹If detections were not observed, analyte concentration is shown as less than the instrument detection limit.




Table 2: Manually-Logged Real-Time Air Monitoring Summary: Worker Breathing Zone
June 28, 2016 17:00 to June 29, 2016 12:00


Analyte	Count of Readings	Count of Detects	Detection Range
CO (ppm)	58	10	1 - 14 ppm
LEL (%)	6	0	< 1 %
NO (ppm)	28	0	< 0.1 ppm
PM2.5 (mg/m3)	52	52	0.003 - 3.420 mg/m3
SO2 (ppm)	22	2	0.2 - 0.3 ppm
VOC (ppm)	64	7	0.1 - 0.6 ppm

¹If detections were not observed, analyte concentration is shown as less than the instrument detection limit.

Attachment A:

Incident Maps






Legend

- Creek/Stream
- Water Body

Elevation (m)


- < 1020 m
- 1021 m - 1025 m
- 1026 m - 1030 m
- 1031 m - 1035 m
- 1036 m - 1040 m
- 1041 m - 1045 m
- 1046 m - 1050 m
- 1051 m - 1055 m
- 1056 m - 1060 m
- > 1060 m




Legend

- A Analytical Sampling Station
- X Incident Site

Analytical sampling was conducted for the following profiles at each location: Metals, Aldehydes, PNAHs, and Hydrocarbons







Legend

F FRT Location

X Incident Site

Monitoring Location

- Community Reading < 0.138 mg/m³
- Community Reading > 0.138 mg/m³
- Work Area Reading < 0.351 mg/m³
- Work Area Reading > 0.351 mg/m³

Panhandle, TX
BNSF Train Collision/Fire

Summary of Air Monitoring Results

June 30, 2016

*Prepared by
Center for Toxicology and Environmental Health, L.L.C.*

Introduction

This report summarizes the work conducted by Center for Toxicology and Environmental Health, LLC (CTEH®) in response to a request for air monitoring support by BNSF Railway following the head-on collision and subsequent fire of locomotives and intermodal cars near Panhandle, TX. On June 29, 2016, CTEH® conducted real-time air monitoring to evaluate the potential presence of acrylates, carbon monoxide (CO), ethyl acetate, nitrogen oxide (NO), particulate matter (PM_{2.5}), sulfur dioxide (SO₂), and total volatile organic compounds (VOCs). This submittal summarizes real-time air monitoring data recorded on CTEH® instrumentation between June 29, 2016 7:00 and June 30, 2016 07:00.

Real-time Air Monitoring

CTEH® efforts consisted of manually-logged real-time air monitoring using handheld instrumentation. Real-time air monitoring was conducted to assess air quality in the community as well as the breathing zone of workers involved in the response. Monitoring was conducted using instruments such as the RAESystems MultiRAE Plus and MultiRAE Pro, and Gastec pumps with chemical-specific colorimetric tubes. Additionally, a DustTrak DRX monitor was set to log PM_{2.5} concentrations near the BNSF staging area near the baseball field adjacent to the derailment site. **Table 1** summarizes the air monitoring data for manually-logged real-time readings in the community. **Table 2** summarizes the air monitoring data for manually-logged real-time readings taken to assess worker breathing zone air quality. **Attachment A** contains incident maps including site location, topography and hydrography, and manually-logged handheld real-time reading locations. **Attachment B** contains a trend graph depicting PM_{2.5} concentrations from the data-logged DustTrak monitor.

Analytical Air Sampling

CTEH® efforts consisted of deploying analytical sampling media at four locations to collect samples for the following profiles: metals, aldehydes, polynuclear aromatic hydrocarbons (PNAHs), and volatile organics using integrated sampling pumps and Minicans. Sampling for metals, aldehydes, and PNAHs are run in concurrent 12 hour periods. The hydrocarbon profile sampling period is 24 hours.

All samples will be sent to an American Industrial Hygiene-accredited analytical testing lab and results reported in future submittals as they become available.

Table 1: Manually-Logged Real-Time Air Monitoring Summary: Community Breathing Zone
June 29, 2016 17:00 to June 30, 2016 07:00

Analyte	Count of Readings	Count of Detects	Detection Range
CO (ppm)	125	0	< 1 ppm
NO (ppm)	23	0	< 0.1 ppm
PM2.5 (mg/m3)	124	124	0.002 – 0.893 mg/m3
SO2 (ppm)	27	0	< 0.1 ppm
VOC (ppm)	122	0	< 0.1 ppm

¹If detections were not observed, analyte concentration is shown as less than the instrument detection limit.

Table 2: Manually-Logged Real-Time Air Monitoring Summary: Worker Breathing Zone
June 29, 2016 7:00 to June 30, 2016 07:00




Analyte	Count of Readings	Count of Detects	Detection Range
² Acrylates	6	0	< 2 ppm
CO (ppm)	12	0	< 1 ppm
Ethyl Acetate	1	0	< 1 %
NO (ppm)	6	0	< 0.1 ppm
PM2.5 (mg/m3)	3	0	0.009 – 0.055 mg/m3
SO2 (ppm)	10	0	0.2 - 0.3 ppm
VOC (ppm)	13	2	1.3 – 1.5 ppm


¹If detections were not observed, analyte concentration is shown as less than the instrument detection limit

²Acrylates monitored using butyl acetate colorimetric tube with a correction factor of 0.7 for butyl acrylate and 0.26 for isobutyl acrylate

Attachment A:

Incident Maps






Legend

- Creek/Stream
- Water Body

Elevation (m)


- < 1020 m
- 1021 m - 1025 m
- 1026 m - 1030 m
- 1031 m - 1035 m
- 1036 m - 1040 m
- 1041 m - 1045 m
- 1046 m - 1050 m
- 1051 m - 1055 m
- 1056 m - 1060 m
- > 1060 m



Legend


- A Analytical Sampling Station
- X Incident Site

Analytical sampling was conducted for the following profiles at each location: Metals, Aldehydes, PNAHs, and Hydrocarbons



Legend

-  FRT Location
-  Incident Site




Legend

- FRT Location
- Incident Site
- Monitoring Location



Attachment B:

DustTrak PM_{2.5} Trend Graph



Data is considered preliminary and subject to additional QA/QC measures


5-min Rolling Avg
Instantaneous



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160628_195630.jpg
Date and Time: Jun 28 2016 12:00AM
Latitude: 35.346779
Longitude: -101.368300
Photographer: 11682
Witness: TEDD
Caption: Incident location - West bound railcars



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160628_200606.jpg
Date and Time: Jun 28 2016 12:00AM
Latitude: 35.346944
Longitude: -101.368333
Photographer: 11682
Witness: TEDD
Caption: Incident location - West bound engine



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160628_194122.jpg
Date and Time: Jun 28 2016 12:00AM
Latitude: 33.056695
Longitude: -96.841517
Photographer: 11682
Witness: TEDD
Caption: EOC information board




Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160628_195650.jpg
Date and Time: Jun 28 2016 12:00AM
Latitude: 35.346779
Longitude: -101.368300
Photographer: 11682
Witness: TEDD
Caption: Incident location - Point of impact - Railcars smoldering



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160628_195858.jpg
Date and Time: Jun 28 2016 12:00AM
Latitude: 35.347359
Longitude: -101.368425
Photographer: 11682
Witness: TEDD
Caption: Incident location - Point of impact - Railcars smoldering



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160628_200605.jpg
Date and Time: Jun 28 2016 12:00AM
Latitude: 35.346944
Longitude: -101.368333
Photographer: 11682
Witness: TEDD
Caption: Incident location - West bound engine



Incident Name:	BNSF Train Collision
Event Name:	BNSF Train Collision
Photo Type:	
Direction:	
Photo Name:	20160628_194131.jpg
Date and Time:	Jun 28 2016 12:00AM
Latitude:	33.056695
Longitude:	-96.841517
Photographer:	11682
Witness:	TEDD
Caption:	EOC information board



Incident Name:	BNSF Train Collision
Event Name:	BNSF Train Collision
Photo Type:	
Direction:	
Photo Name:	20160628_195938.jpg
Date and Time:	Jun 28 2016 12:00AM
Latitude:	35.347359
Longitude:	-101.368425
Photographer:	11682
Witness:	TEDD
Caption:	Incident location - Smoke migrating north-northwest



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160628_195404 2.jpg
Date and Time: Jun 28 2016 12:00AM
Latitude: 35.345967
Longitude: -101.372241
Photographer: 11682
Witness: TEDD
Caption:

Incident location - Point of impact - Railcars smoldering - Eastbound railcars



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160628_195632.jpg
Date and Time: Jun 28 2016 12:00AM
Latitude: 35.346779
Longitude: -101.368300
Photographer: 11682
Witness: TEDD
Caption:

Incident location - West bound railcars



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160628_195652.jpg
Date and Time: Jun 28 2016 12:00AM
Latitude: 35.346779
Longitude: -101.368300
Photographer: 11682
Witness: TEDD
Caption: Incident location - Point of impact - Railcars smoldering



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160628_195939.jpg
Date and Time: Jun 28 2016 12:00AM
Latitude: 35.347359
Longitude: -101.368425
Photographer: 11682
Witness: TEDD
Caption: Incident location - Smoke migrating north-northwest



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160628_195850.jpg
Date and Time: Jun 28 2016 12:00AM
Latitude: 35.347222
Longitude: -101.368333
Photographer: 11682
Witness: TEDD
Caption: Incident location - Point of impact - Railcars smoldering



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160628_195857.jpg
Date and Time: Jun 28 2016 12:00AM
Latitude: 35.347359
Longitude: -101.368425
Photographer: 11682
Witness: TEDD
Caption: Incident location - Point of impact - Railcars smoldering



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160628_195941.jpg
Date and Time: Jun 28 2016 12:00AM
Latitude: 35.347359
Longitude: -101.368425
Photographer: 11682
Witness: TEDD
Caption: Incident location - Smoke migrating north-northwest



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160629_093347.jpg
Date and Time: Jun 29 2016 12:00AM
Latitude: 35.343100
Longitude: -101.368960
Photographer: 11682
Witness: TEDD
Caption: Fixed Real Time Air Monitoring - 1



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160629_113638.jpg
Date and Time: Jun 29 2016 12:00AM
Latitude: 35.348459
Longitude: -101.371591
Photographer: 11682
Witness: TEDD
Caption: Fixed Real Time Air Monitoring - 12



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160629_113121.jpg
Date and Time: Jun 29 2016 12:00AM
Latitude: 35.346723
Longitude: -101.370888
Photographer: 11682
Witness: TEDD
Caption: Fixed Real Time Air Monitoring - 11



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160629_093353.jpg
Date and Time: Jun 29 2016 12:00AM
Latitude: 35.343100
Longitude: -101.368960
Photographer: 11682
Witness: TEDD
Caption: Fixed Real Time Air Monitoring - 1



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160629_113648.jpg
Date and Time: Jun 29 2016 12:00AM
Latitude: 35.348459
Longitude: -101.371591
Photographer: 11682
Witness: TEDD
Caption: Fixed Real Time Air Monitoring - 12



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160629_095430.jpg
Date and Time: Jun 29 2016 12:00AM
Latitude: 35.340754
Longitude: -101.375765
Photographer: 11682
Witness: TEDD
Caption: Fixed Real Time Air Monitoring - 3



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160629_095407.jpg
Date and Time: Jun 29 2016 12:00AM
Latitude: 35.340754
Longitude: -101.375765
Photographer: 11682
Witness: TEDD
Caption: Fixed Real Time Air Monitoring - 3



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160629_094052.jpg
Date and Time: Jun 29 2016 12:00AM
Latitude: 35.345581
Longitude: -101.366038
Photographer: 11682
Witness: TEDD
Caption: Point of Impact - East Bound Train



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160629_102004.jpg
Date and Time: Jun 29 2016 12:00AM
Latitude: 35.342885
Longitude: -101.377833
Photographer: 11682
Witness: TEDD
Caption: Fixed Real Time Air Monitoring - 4



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160629_111539.jpg
Date and Time: Jun 29 2016 12:00AM
Latitude: 35.345875
Longitude: -101.375272
Photographer: 11682
Witness: TEDD
Caption: Fixed Real Time Air Monitoring - 7



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160629_102715.jpg
Date and Time: Jun 29 2016 12:00AM
Latitude: 35.345279
Longitude: -101.378869
Photographer: 11682
Witness: TEDD
Caption: Fixed Real Time Air Monitoring - 5



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160629_094033.jpg
Date and Time: Jun 29 2016 12:00AM
Latitude: 35.345581
Longitude: -101.366038
Photographer: 11682
Witness: TEDD
Caption: Point of Impact - West Bound Train



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160629_105027.jpg
Date and Time: Jun 29 2016 12:00AM
Latitude: 35.348893
Longitude: -101.381327
Photographer: 11682
Witness: TEDD
Caption: Fixed Real Time Air Monitoring - 6



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160629_094041.jpg
Date and Time: Jun 29 2016 12:00AM
Latitude: 35.345581
Longitude: -101.366038
Photographer: 11682
Witness: TEDD
Caption: Point of Impact



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160629_094519.jpg
Date and Time: Jun 29 2016 12:00AM
Latitude: 35.342500
Longitude: -101.372040
Photographer: 11682
Witness: TEDD
Caption: Fixed Real Time Air Monitoring - 2



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160629_113118.jpg
Date and Time: Jun 29 2016 12:00AM
Latitude: 35.346723
Longitude: -101.370888
Photographer: 11682
Witness: TEDD
Caption: Fixed Real Time Air Monitoring - 11



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160629_094040.jpg
Date and Time: Jun 29 2016 12:00AM
Latitude: 35.345581
Longitude: -101.366038
Photographer: 11682
Witness: TEDD
Caption: Point of Impact - West Bound Train



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160629_111552.jpg
Date and Time: Jun 29 2016 12:00AM
Latitude: 35.345875
Longitude: -101.375272
Photographer: 11682
Witness: TEDD
Caption: Fixed Real Time Air Monitoring - 7



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160629_101956.jpg
Date and Time: Jun 29 2016 12:00AM
Latitude: 35.343091
Longitude: -101.378696
Photographer: 11682
Witness: TEDD
Caption: Fixed Real Time Air Monitoring - 4



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160629_102726.jpg
Date and Time: Jun 29 2016 12:00AM
Latitude: 35.345279
Longitude: -101.378869
Photographer: 11682
Witness: TEDD
Caption: Fixed Real Time Air Monitoring - 5



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160629_093400.jpg
Date and Time: Jun 29 2016 12:00AM
Latitude: 35.343055
Longitude: -101.368888
Photographer: 11682
Witness: TEDD
Caption: Fixed Real Time Air Monitoring - 1



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160629_113114.jpg
Date and Time: Jun 29 2016 12:00AM
Latitude: 35.346723
Longitude: -101.370888
Photographer: 11682
Witness: TEDD
Caption: Fixed Real Time Air Monitoring - 11



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160629_094032.jpg
Date and Time: Jun 29 2016 12:00AM
Latitude: 35.345581
Longitude: -101.366038
Photographer: 11682
Witness: TEDD
Caption: Point of Impact - West Bound Train



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160629_095355.jpg
Date and Time: Jun 29 2016 12:00AM
Latitude: 35.340754
Longitude: -101.375765
Photographer: 11682
Witness: TEDD
Caption: Fixed Real Time Air Monitoring - 3



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160629_094039.jpg
Date and Time: Jun 29 2016 12:00AM
Latitude: 35.345581
Longitude: -101.366038
Photographer: 11682
Witness: TEDD
Caption: Point of Impact - West Bound Train



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160629_105039.jpg
Date and Time: Jun 29 2016 12:00AM
Latitude: 35.348893
Longitude: -101.381327
Photographer: 11682
Witness: TEDD
Caption: Fixed Real Time Air Monitoring - 6



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160629_093348.jpg
Date and Time: Jun 29 2016 12:00AM
Latitude: 35.343100
Longitude: -101.368960
Photographer: 11682
Witness: TEDD
Caption: Fixed Real Time Air Monitoring - 1



Incident Name: BNSF Train Collision
Event Name: BNSF Train Collision
Photo Type:
Direction:
Photo Name: 20160629_094458.jpg
Date and Time: Jun 29 2016 12:00AM
Latitude: 35.342500
Longitude: -101.372040
Photographer: 11682
Witness: TEDD
Caption: Fixed Real Time Air Monitoring - 2

Incident Name: undefined
Event Name: undefined
Photo Type: undefined
Direction: undefined
Photo Name: undefined
Date and Time: undefined
Latitude: undefined
Longitude: undefined
Photographer: undefined
Witness: undefined
Caption: undefined

[Submit Action Report](#)[Spill Summary Report](#)

NATIONAL RESPONSE CENTER 1-800-424-8802

GOVERNMENT USE ONLYGOVERNMENT USE ONLY***

Information released to a third party shall comply with any applicable federal and/or state Freedom of Information and Privacy Laws

Incident Report # 1151859

INCIDENT DESCRIPTION

*Report taken by: MST3 STEPHEN COOKE at 10:24 on 28-JUN-16

Incident Type: RAILROAD

Incident Cause: DERAILMENT

Affected Area:

Incident occurred on 28-JUN-16 at 08:25 local incident time.

Affected Medium: BALLAST UNKNOWN AMOUNT OF DIESEL ON BALLAST

REPORTING PARTY

Name: GARY KETCHAM

Organization: BNSF

Address: 2600 LOU MENK DR.

FORT WORTH, TX

PRIMARY Phone: (817)3522832

Type of Organization: PRIVATE ENTERPRISE

SUSPECTED RESPONSIBLE PARTY

Name: GARY KETCHAM

Organization: BNSF

Address: 2600 LOU MENK DR.

FORT WORTH, TX

PRIMARY Phone: (817)3522832

Type of Organization: PRIVATE ENTERPRISE

INCIDENT LOCATION

MP: 524 County: CARSON

SD: PANHANDLE

State: TX

RELEASED MATERIAL(S)

CHRIS Code: ODS Official Material Name: OIL: DIESEL

Also Known As:

Qty Released: 0 UNKNOWN AMOUNT

DESCRIPTION OF INCIDENT

CALLER IS REPORTING A HEAD ON COLLISION BETWEEN TWO LOCOMOTIVES DUE TO UNKNOWN CAUSES. THERE IS AN UNKNOWN AMOUNT OF DIESEL FUEL THAT DISCHARGED ONTO THE BALLAST. THREE LOCOMOTIVES HAVE BEEN DESTROYED WITH AN UNKNOWN AMOUNT OF RAILCARS DERAILED.

INCIDENT DETAILS

Grade Crossing: NO

Location Subdivision: PANHANDLE

Railroad Milepost: 524

Type of Vehicle Involved:

Crossing Device Type:

Device Operational: YES

DOT Crossing Number:

Date and Time Service was/will be Restored:

Brake Failure: UNKNOWN

Federal Post-Accident 219.201 Sub Part C Testing Required: YES

Counts and Types of Employees Tested are UNKNOWN

Passenger Train Route: NO
 Passenger Train Delay Expected: NO
 Passenger Train Delay Handling:

---RAILROAD INFORMATION---

Railroad Involved: BNSF
 Train Number: QCHISBD627
 Train Type: FREIGHT Train Direction:
 Train Speed: Track Speed:
 Locomotives: Cars: Derailed:
 Suspected DOT Regulation Non Compliance: UNKNOWN
 DERAILED CARS:

Pos.	Carnumber	Type	Cargo
------	-----------	------	-------

---RAILROAD INFORMATION---

Railroad Involved: BNSF
 Train Number: SLACLPC126
 Train Type: FREIGHT Train Direction:
 Train Speed: Track Speed:
 Locomotives: Cars: Derailed:
 Suspected DOT Regulation Non Compliance: UNKNOWN
 DERAILED CARS:

Pos.	Carnumber	Type	Cargo
------	-----------	------	-------

IMPACT

Fire Involved: YES Fire Extinguished: NO
 INJURIES: YES 4 Hospitalized: 1 Empl/Crew: 4 Passenger: 0
 FATALITIES: UNKNOWN Empl/Crew: Passenger: Occupant:
 EVACUATIONS: NO Who Evacuated: Radius/Area:
 Damages: UNKNOWN

<u>Closure Type</u>	<u>Description of Closure</u>	<u>Hours Closed</u>	<u>Direction of Closure</u>
Air:	N		
Road:	N		Major Artery: N
Waterway:	N		
Track:	Y MAIN TRACKS		E/W

Passengers Transferred: NO
 Environmental Impact: UNKNOWN
 Media Interest: UNKNOWN Community Impact due to Material:

REMEDIAL ACTIONS

WILL CONTACT AN ENVIRONMENTAL RESPONSE CONTRACTOR TO HANDLE THE DIESEL RELEASE.

Release Secured: NO
 Release Rate:
 Estimated Release Duration:

WEATHER

ADDITIONAL AGENCIES NOTIFIED

Federal:
 State/Local:
 State/Local On Scene:
 State Agency Number:

NOTIFICATIONS BY NRC

CENTERS FOR DISEASE CONTROL (GRASP)
 28-JUN-16 10:40 (770)4887100

NATIONAL COORDINATING CTR FOR COMMS (NCC COMM-ISAC)
28-JUN-16 10:40 (703)2355626
DHS TEXAS FUSION CENTER (INTELLIGENCE OFFICERS)
28-JUN-16 10:40 (202)3068204
DOT CRISIS MANAGEMENT CENTER (MAIN OFFICE)
28-JUN-16 10:40 (202)3661863
FEDERAL RAILROAD ADMIN. (MAIN OFFICE)
28-JUN-16 10:43 (202)4936242 TALLY
FEDERAL RAILROAD ADMIN. (ACCIDENT AND ANALYSIS BRANCH)
28-JUN-16 10:43 (817)9141723 TALLY
EPA HQ EMERGENCY OPERATIONS CENTER (MAIN OFFICE)
28-JUN-16 10:40 (202)5643850
EPA OEM (MAIN OFFICE)
28-JUN-16 10:49 (202)5643850 FAULKNER
U.S. EPA VI (MAIN OFFICE)
28-JUN-16 10:44 (866)3727745 BERNEAR
USCG NATIONAL COMMAND CENTER (MAIN OFFICE)
28-JUN-16 10:40 (202)3722100
JFO-LA (COMMAND CENTER)
28-JUN-16 10:40 (225)3366513
NATIONAL INFRASTRUCTURE COORD CTR (MAIN OFFICE)
28-JUN-16 10:40 (202)2829201
NOAA RPTS FOR TX (MAIN OFFICE)
28-JUN-16 10:40 (206)5264911
NATIONAL RESPONSE CENTER HQ (MAIN OFFICE)
28-JUN-16 10:40
NATIONAL RESPONSE CENTER HQ (AUTOMATIC REPORTS)
28-JUN-16 10:40 (202)2671136
NRC COMMAND DUTY OFFICER (MAIN OFFICE)
28-JUN-16 10:51 (202)2672100 CARTER
NTSB RAIL (MAIN OFFICE)
28-JUN-16 10:40 (202)3146293
HOMELAND SEC COORDINATION CENTER (MAIN OFFICE)
28-JUN-16 10:40 (202)2828300
PIPELINE & HAZMAT SAFETY ADMIN (OFFICE HAZARDOUS MATERIALS)
28-JUN-16 10:50 (202)3661863 CARTER
PIPELINE & HAZMAT SAFETY ADMIN (OFFICE HAZARDOUS MATERIALS FAX#2)
28-JUN-16 10:40 (202)3661863
SAN ANTONIO POLICE DEPT (SOUTHWEST FUSION CENTER (SWFC))
28-JUN-16 10:40 (210)2077680
TCEQ (MAIN OFFICE)
28-JUN-16 10:40 (800)8328224
TCEQ (REGION 1)
28-JUN-16 10:40 (512)2392507
TEXAS DEPARTMENT OF TRANSPORTATION (RAIL SAFETY SECTION)
28-JUN-16 10:40 (512)4163244
TEXAS FUSION CENTER (COUNTER TERRORISM)
28-JUN-16 10:40 (866)7865972
TEXAS STATE OPERATIONS CENTER (COMMAND CENTER)
28-JUN-16 10:40 (512)4242208
USCG DISTRICT 8 (MAIN OFFICE)
28-JUN-16 10:40 (504)5896225
USCG DISTRICT 8 (PLANNING)
28-JUN-16 10:40 (504)6712080

ADDITIONAL INFORMATION

IT IS ESTIMATED THAT A FEW THOUSAND GALLONS OF DIESEL HAS BEEN RELEASED,
BUT QUANTITIES ARE UNKNOWN AT THIS TIME. THERE ARE THREE RAIL EMPLOYEES
MISSING AT THIS TIME, THEIR HEALTH AND WELL BEING IS UNKNOWN. INITIAL
DAMAGE ESTIMATES WILL EXCEED A MILLION DOLLARS.

*** END INCIDENT REPORT # 1151859 ***
Report any problems by calling 1-800-424-8802
PLEASE VISIT OUR WEB SITE AT <http://www.nrc.uscg.mil>

Close Window

DEFYING
MOTHER NATURE™

SINCE 1916



All components of
this product are recyclable

Rite in the Rain

A patented, environmentally
responsible, all-weather writing paper
that sheds water and enables you to
write anywhere, in any weather.

Using a pencil or all-weather pen,
Rite in the Rain ensures that your
notes survive the rigors of the field,
regardless of the conditions.

© 2015

JL DARLING LLC
Tacoma, WA 98424-1017 USA
www.RiteintheRain.com

Item No. 391FX
ISBN: 978-1-60134-188-4

Made in the USA
US Pat. No. 6,863,940



Rite in the Rain

ALL-WEATHER
JOURNAL

No 391FX

BNSF Panhandle Derailment
VO# 20406.012.001. 10/19.01
Weston Solutions, Inc.
3900 Dallas Pkwy. Suite 175
Plano, TX 75093
Book 1 of 1

MADE IN TACOMA

— SINCE 1916 —

Rite in the Rain

= DEFYING MOTHER NATURE =

Name

Ad

Ph

Pro

*The Trusted Integrator for Sustainable Solutions*

Weston Solutions, Inc.
 Suite 175
 3900 Dallas Parkway
 Plano, TX 75093

JOSE L. OJEDA

SENIOR PROJECT LEADER
 START TEAM

469-666-5506
 cell: 619-417-3298
 fax: 469-666-5540
 jose.ojeda@westonsolutions.com
 www.westonsolutions.com

an employee-owned company **RiteintheRain.com****CONTENTS**

PAGE

REFERENCE

DATE

START-3 PTL Jose Ojeda

BNSF Panhandle Derailment

June 28 2016 20406.012.001.1019.01
 1319 Depart Weston Office to CCO? — dr
 1324 Arrive @ CCOPT & load Uper System; — dr
 2 ARAEs; 1 VRAE; 2 Hazdust; 2 H₂S Badges
 1 Dragger Kit w/ chips. — dr
 1345 Exit CCOPT. Begin drive to incident — dr
 START-3 Personnel: Jose Cal. & Oscar Garcia
 EPA: OSC Bill Rhotenberg — dr
 Current Onsite Contacts: — dr
 TCEQ Susan Thompson 806-517-0972 — dr
 Railroad Gary Ketchum 817-352-2832 — dr
 1929 Arrive @ Carson County Law Enforcement
 Center in Panhandle, TX — dr
 1955 Met at command post with OSC Rhotenberg,
 TCEQ Chris Podcenny 806-468-0519; Jason
 Pruitt 806 468 0513; Susan Thompson 806-552-517-
 -0972; DPS Joe Minshew & Chad Grange; DSHS
 Jordan Coulson; County Attorney Scott Sherwood is
 the PIO; NWS Lance Goehring; Pontex, Chuck
 477-5959; Ty Davis, works with anhydrous ammonia;
 1946 Departed govt center with OSC Rhotenberg.
 1935 Arrived northwest side of incident. — dr
 612 760 1365 Derrick Lamkin. — dr
 2008 Met Derrick Lamkin, BNSF Hazmat. Met — dr
 two CTEH representatives. 14 real time locations — dr
 throughout community set up. Winds have changed
 recently, towards residences; workers actively — dr

BNSF Panhandle Derailment

20406.012.001.1019.01 June 28 2016
 Working on smoldering cars. High PM levels found downwind.
 CTEH will have 24 hr monitoring. Firefighters will — dr
 remain overnight, cannot wreck yet due to investigation
 Also, will have hourly averages PM 2.5, PM 10. — dr
 CTEH req D.J. Fogelman 501-813-6591, and Dr. Paul
 Ho Nong toxicologist. 501-352-3131 — dr
 2030 OSC Rhotenberg spoke with local EOC rep, — dr
 we will meet at same govt center at 0800. — dr
 2050 EPA Team departs incident site, to EOC. — dr
 2115 Started MultiRAE, zeroed/initialized both — dr
 DataRAMs. — dr
 2130 Fresh air cal MultiRAE. All sensors PASS. — dr
 O₂ 18.1. 18.1. LEL 50%. 49%. — dr
 CO 5ppm 50 ppm H₂S 10.0 ppm 10.0 ppm — dr
 All PASS. — dr
 VOC PASS, Isobutylene 100 ppm. 110.3 ppm. — dr
 2142 MultiRAE #23798 All sensors PASS. — dr
 2144 Started running both DataRAMs. — dr
 2150 Weather: partly cloudy 82°F, 15% chance precip.
 humidity 48%, wind SE 11 mph; Forecast: scattered
 thunderstorms at 0700 tomorrow, 6/29/16. — dr
 2225 EPA team departs EOC to community — dr
 locations to test DataRAMs, North 5th St. and
 Green St.; Measured 0.03 mg/m³, and 1.60 mg/m³
 at next street corner. Both max readings.

BNSF Panhandle Derailment

June 29 2016

20406.01/2.001.10/9.01

0730 EPA Team departed hotel, ————— dr

0800 Arrived at EOC and awaited local refs. ————— dr

0845 Started datarans, initialized and running. ————— dr

Mult-RAE calibration ————— dr

Fresh air cal PASS. and All sensors PASS. ————— dr

Oxy 18% LEL 50% ————— dr

CO 50 ppm H₂S 10.1 ppm ————— dr

VOC Isobutylene 100.1 ————— dr

0918 Arrived onsite with TCEQ Susan and Jason. ————— dr

met with CTEH BJ Fogleman. ————— dr

0930 Ride with CTEH Josh, with 2 datarans, first location off of highway Id. FRT1, .003 mg/m³ avg. ————— dr

0942 FRT2, .006 mg/m³ avg ————— dr

0953 FRT3, .002 mg/m³ avg ————— dr

1012 FRT4, .003 mg/m³ avg ————— dr

1027 FRT5, .007 mg/m³ avg ————— dr

1035 FRT6, .005 mg/m³ avg — TCEQ departs from our monitoring round ————— dr

1042 FRT7, .003 mg/m³ avg ————— dr

1055 FRT8, .004 mg/m³ avg ————— dr

1108 FRT9, .001 mg/m³ avg ————— dr

1116 FRT10, .005 mg/m³ avg ————— dr

1127 FRT11, .002 mg/m³ avg ————— dr

1136 FRT12, .003 mg/m³ avg ————— dr

1146 FRT13, .002 mg/m³ avg ————— dr

1200 Met at CTEH trailer, ————— dr

BNSF Panhandle Derailment

20406.01/2.001.10/9.01

June 29 2016

1219 Rhotenberg in CTEH trailer, discuss progress. ————— dr

Doug McKeenolds BNSF point of contact, 817-304-2031

1220 Notes from CTEH air monitoring round: their monitor was consistently reading ~0.006 mg/m³ higher than our datarans. Josh said may need to clean his monitor's inlet tube. ————— dr

1230 EPA Team offsite. ————— dr

1930 Arrived at DTX office. ————— dr

End of Logbook. ————— dr

Business cards on page 48 ————— dr

~~Done~~
June 29, 2016

6
20406.012.001.1019.01

~~Jose [Signature]
June 29, 2016~~

7
BNSF Pantanillo Derailment

~~Jose [Signature]
June 29, 2016~~

20406.012.001, 10/9.01

Jose (1) Sch
June 29, 2016

BNSF Parallel Derailment

Jose (1) Sch
June 29, 2016

20406.012.001.1019.01

Jose O. Lopez
June 29, 2016


BUSF Panhandle Derailment

Jose O. Lopez
June 29, 2016

20406.012.001.10/9.01


 June 29, 2016

BNSF Panhandle Newsletter


 June 29, 2016

20906, 012.001.1019.01

Jose
June 29, 2016

BNSF Panhandle Derailment

Jose
June 29, 2016


20406, 012, 001, 1019.01

Jose
June 29, 2016


BWSF Pantanillo Demolition

Jose
June 29, 2016

20406, 012.001, 1019.01


 Jose
 June 29, 2016

BNSF Porthandle Disinfectant


 Jose
 June 29, 2016

20906.012.001.1019.01

Jose Ojeda
June 29, 2016

BNSF Panhandle Derailment

Jose Ojeda
June 29, 2016

20906.012.001.1019.01

Jose - Oh
June 29, 2016


BNSF Pantanillo Derailment

Jose - Oh
June 29, 2016


20406.012.001.10A.01


 June 29, 2014


BNSF Panhandle Derailment


 June 29, 2014

20406, 012, 001, 1019.01


 Jose
 June 29, 2016

BNSF Panhandle Derailment


 Jose
 June 29, 2016

20906, 012, 001, 1019.01

Jose O. Salas
June 29, 2016

 BUS F Panhandle Derailment ²⁹

Jose O. Salas
June 29, 2016

20406.012.001, 10/19.01

Jose
June 29, 2014


BNSF Panhandle Derailment

Jose
June 29, 2014


20406.012.001.1019.01


 Jose
 June 24, 2016


BNSF Panhandle Damblment ³³


 Jose
 June 29, 2016


20406.012.001.1019.01


 June 29, 2016


BNSF Parkville Department ³⁵


 June 29, 2016


20406, 012, 001, 10/19.01


 Jose
 June 29, 2016


BNSF Panhandle Derrilment


 Jose
 June 29, 2016

20406.012.001.10A.01


 Jose
 June 29, 2016

39
3USF Panhandle Department


 Jose
 June 29, 2016


20406, 012.001, 10/19.01

Jose
June 29, 2016


BUSF Panhandle Department

Jose
June 29, 2016


2006.012.001.6A.01


 Jose (Oh)
 June 29, 2014


 BNSF Panhandle Detachment ⁴³


 Jose (Oh)
 June 29, 2014

2016.012.001.1019.01


 June 29, 2016

20 BUST Panhandle Derailment



 June 29, 2016

20406.012.001.10A.01



 June 29, 2016

 BUS F Parkville Detachment ²⁷



 June 29, 2016

CHRIS PODZEMNY

Environmental Investigator
Field Operations Division

Region 1 ■ Amarillo



Texas Commission on Environmental Quality

3918 Canyon Drive, Amarillo, TX 79109
Direct: 806/468-0519 ■ Office: 806/353-9251
Fax: 806/358-9545
christopher.podzemny@tceq.texas.gov

printed on recycled paper




**CENTER FOR TOXICOLOGY
AND ENVIRONMENTAL HEALTH, LLC**

Bradley J. Fogleman

Environmental Scientist
TERP Project Manager

5120 Northshore Drive ■ North Little Rock, AR 72118
t: 501.801.8669 ■ c: 501.813.6591
bfogleman@cteh.com

*Josh-Oh
June 29, 2014*



USE WET OR DRY
most pens stop writing when wet

- ALL PENCILS
- RITE IN THE RAIN PENS
- WAX MARKERS
- CRAYONS
- OIL PASTELS / PAINT

WHEN DRY ONLY
what you write won't wash off

- PERMANENT MARKERS
- STANDARD BALLPOINTS

WON'T WORK
water-based inks bead off sheet

- GEL PENS
- MOST HIGHLIGHTERS
- FOUNTAIN PENS
- WATER COLORS
- ACRYLIC PAINT

MADE IN TACOMA

SINCE 1916

Rite in the Rain
DEFYING MOTHER NATURE

Yes, Rite in the Rain
is a wood-based & recyclable
paper, but unlike plain paper...
it won't turn to mush
when exposed to:



ALL-WEATHER TOUGH!




The Rite in the Rain story began nearly a century ago in the forests of the Great Northwest. Entrepreneur, Jerry Darling, recognized the logging industry's need for a durable material that could be written on and survive in poor weather conditions. Jerry developed a special coating that created a unique moisture shield on the hand-dipped sheets of paper that he and his wife, Mary, processed at their home.

From humble beginnings our first all-weather paper was born! Over the many years we've perfected and patented our environmentally responsible coating process. Still located in Tacoma, our continued mission is to provide innovative products for professionals and enthusiasts who brave the outdoors.

EQUIPPING MULTIPLE INDUSTRIES WORLD-WIDE



other product styles available



RiteintheRain.com

©JL DARLING LLC
2614 PACIFIC HWY EAST,
TACOMA, WA 98424 USA



U.S. ENVIRONMENTAL PROTECTION AGENCY
POLLUTION/SITUATION REPORT
BNSF Panhandle Derailment - Removal Polrep
Initial Removal Polrep



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
Region VI

Subject: POLREP #1
Initial
BNSF Panhandle Derailment

Panhandle, TX
Latitude: 35.3468044 Longitude: -101.3654968

To: Reggie Cheatham, Office of Emergency Management
Ronnie Crossland, Superfund Division
Anthony Buck, TCEQ ER

From: William Rhotenberry, FOSC

Date: 6/29/2016

Reporting Period: 6/28-29/2016

1. Introduction

1.1 Background

Site Number:	A6NJ	Contract Number:	
D.O. Number:		Action Memo Date:	
Response Authority:	CERCLA	Response Type:	Emergency
Response Lead:	EPA	Incident Category:	Removal Assessment
NPL Status:	Non NPL	Operable Unit:	
Mobilization Date:	6/28/2016	Start Date:	6/28/2016
Demob Date:	6/29/2016	Completion Date:	
CERCLIS ID:		RCRIS ID:	
ERNS No.:		State Notification:	
FPN#:		Reimbursable Account #:	

1.1.1 Incident Category

This incident is an Emergency Response due to fire from locomotive engines involved in the collision, resulting in a smoke plume with potential impacts to the town of Panhandle, as well as damage to two railcars containing hazardous materials. BNSF Railway is the Responsible Party (RP).

1.1.2 Site Description

On 28 June 2016 at approximately 0825 CST, two BNSF Railway (BNSF) freight trains collided in Panhandle, Carson County, Texas on the main line known as the Southern Transcon. Initial information received in the National Response Center (NRC Report #1151859) reported an unknown amount of diesel fuel spilled onto the ballast of the rail line. An incident update by BNSF and the Texas Commission on Environmental Quality (TCEQ) reported diesel from the locomotive engines involved in the incident were

burning, with no emergency evacuations or road closures initiated in the area. Due to a weather change at the incident, the smoke plume changed to a northwesterly direction and an evacuation of the area was conducted. Three BNSF personnel are unaccounted for and presumed dead by the Texas Department of Public Safety.

1.1.2.1 Location

The Site is located in Panhandle, TX in Carson County, at 35.3468044°, -101.3654968°. The rail line known as Southern Transcon runs east/west, and is located north of Hwy 60.

1.1.2.2 Description of Threat

Burning diesel from the four locomotive engines (two engines per train), and burning commodities from damaged intermodals caused a plume of smoke to impact the incident location. Changing onsite weather conditions, and changing wind direction prompted an evacuation of a residential area located north-northwest of the incident location. Spilled diesel from the locomotive engines impacted the ballast located on the rail line right of way, soil, and vegetation. No visible impact to water was observed.

The westbound train derailed two locomotives and six railcars. The 6 damaged railcars contained mixed commodities with no hazmat listed on railroad documents. There were 4 railcars containing hazmat that were unaffected.

The eastbound train derailed two locomotives and nine railcars. Railcars 3 and 7 were listed as hazmat on railroad documents. Railcar 3 was listed as UN1866, resin solution (resin solution flammable), and railcar 7 was listed as UN1325, flammable solid, organic, N.O.S. (aluminum). The remaining damaged railcars were listed as mixed commodities with no hazmat listed on railroad documents. The east bound train had 3 other hazmat railcars that were unaffected.

1.1.3 Preliminary Removal Assessment/Removal Site Inspection Results

The EPA and START Contractors arrived in Panhandle, TX at the Carson County Law Enforcement Center at approximately 19:29 on 28 June 2016, and met with Susan Thompson, Jason Pruitt, and Chris Podzemny, Environmental Investigators for the TCEQ Amarillo Region 1 Office. An incident briefing was conducted with the EPA Team, and then the teams proceeded to the incident location.

At the incident location, the EPA Team met with Derrick Lamkin, BNSF representative, and their environmental contractors, CTEH. CTEH described the current air monitoring and sampling operations, which included hourly air monitoring from 13 locations (10 north of Hwy 60, 3 south of Hwy 60) for:

- VOC
- PM 2.5
- CO
- NO
- SO₂

and hourly Air sampling from 4 locations (3 north of Hwy 60, 1 south of Hwy 60) for:

- Aldehydes
- Metals
- PAHs
- VOCs

EPA reviewed the data collected to that point by CTEH. Particulates appeared to be the only potential contaminant of concern. The EPA Team proceeded to locations north of Hwy 60 (directly downwind of incident) to conduct air monitoring utilizing two DataRAM 4™ Particulate Monitors. Particulate readings ranged from 0.03 mg/m³ to 1.60 mg/m³. Prevailing winds were gusting and there were no sustained readings.

On 29 June 2016, the EPA Team and TCEQ Environmental Investigators accompanied CTEH personnel to

conduct air monitoring concurrently at the 13 Fixed Real Time (FRT) monitoring locations. Average particulate readings for the locations ranged from 0.001 to 0.007 milligrams per cubic meter.

At 13:00 on 29 June a discussion was held with BNSF regarding remaining environmental issues. The fire was completely out and there were no remaining air issues related to the fire. Impacted soils from the diesel discharged or from various commodities whose containers were breached and spilled will be excavated, sampled and sent to either a local non-hazardous landfill or to a designated hazardous waste facility per TCEQ instructions and oversight. The condition of the railcar containing the aluminum material will be assessed once BNSF is able to access it.

2. Current Activities

2.1 Operations Section

2.1.1 Narrative

2.1.2 Response Actions to Date

The EPA Team departed the site on 29 June 2016.

2.1.3 Enforcement Activities, Identity of Potentially Responsible Parties (PRPs)

BNSF Railway is the Responsible party

2.1.4 Progress Metrics

<i>Waste Stream</i>	<i>Medium</i>	<i>Quantity</i>	<i>Manifest #</i>	<i>Treatment</i>	<i>Disposal</i>

2.2 Planning Section

2.2.1 Anticipated Activities

BNSF will excavate, sample and properly dispose of all contaminated soils. BNSF will access and take steps to mitigate any releases from the railcar containing the Aluminum material. Air monitoring activities will continue while soil excavation/disposal activities are ongoing.

2.2.1.1 Planned Response Activities

2.2.1.2 Next Steps

2.2.2 Issues

None

2.3 Logistics Section

No information available at this time.

2.4 Finance Section

No information available at this time.

2.5 Other Command Staff

No information available at this time.

3. Participating Entities

3.1 Unified Command

3.2 Cooperating Agencies

TCEQ

Carson County Emergency Management

4. Personnel On Site

Agency Personnel;

1 - EPA FOSC

2 - Weston Solution START Contractors

3 - TCEQ investigators

2 - NTSB Investigators

5. Definition of Terms

No information available at this time.

6. Additional sources of information

No information available at this time.

7. Situational Reference Materials

No information available at this time.

U.S. EPA, Region 6
1445 Ross Avenue, Suite 1200
Dallas, TX 75202-2733
Vendor : WESTON SOLUTIONS, INC.

TDD # : 1/WESTON-042-16-023
Amendment # :
Contract # : EP-W-06-042

TDD Title :BNSF Panhandle Derailment
Purpose : TDD INITIATION

Priority : HIGH
Overtime Authorized : Yes
Invoice Unit :

Verbal Date : 06/28/2016
Start Date : 06/28/2016
Completion Date : 08/15/2016
Effective Date : 06/28/2016

SSID : A6NJ
Project/Site Name : BNSF Panhandle Derailment
Project Address : City of Panhandle
County : Carson
City : Panhandle
State : TX
Zip Code : 79068

Work Area : Response / Removal
Work Area Code : RS
Activity : Fund Lead Removal
Activity Code : RV
Operable Unit :
Emergency Code :
FPN :
Performance Based : No

Authorized TDD Ceiling :	Amount	LOE (Hours)
Previous Action(s) :	\$0.00	0.00
This Action :	\$12,000.00	0.00
New Total :	\$12,000.00	0.00

Specific Elements :
See Schedule

Description of Work :
See Schedule

Region Specific :
CERCLIS : Misc 2 :

Accounting and Appropriation Information:									SFO:	
Line	Budget / FY	Approp	Budget	Program Element	Object Class	Site Project	Cost	DCN Line-ID	Funding Category	TDD Amount
1	16	T	6A00	303DC6	2505	06WQRV00	C001	166ARVC012-001	REMOVAL	\$12,000.00

--

U.S. EPA, Region 6
1445 Ross Avenue, Suite 1200
Dallas, TX 75202-2733

Vendor: WESTON SOLUTIONS, INC.

TDD #: 1/WESTON-042-16-023

Amendment #:

Contract #: EP-W-06-042

Project Officer : Will LaBombard <div style="display: flex; justify-content: space-between; margin-top: 10px;"> <div style="border-bottom: 1px solid black; width: 45%; text-align: center;">(Signature)</div> <div style="border-bottom: 1px solid black; width: 45%; text-align: center;">(Date)</div> </div>	Branch Mail Code: Phone Number : 214-665-7199 Fax Number :
Contracting Officer Representative William Rhotenberry <div style="display: flex; justify-content: space-between; margin-top: 10px;"> <div style="border-bottom: 1px solid black; width: 45%; text-align: center;">(Signature)</div> <div style="border-bottom: 1px solid black; width: 45%; text-align: center;">(Date)</div> </div>	Branch Mail Code : Phone Number : 214-665-8372 Fax Number :
Contract Specialist: Michael J. Pheeny <div style="display: flex; justify-content: space-between; margin-top: 10px;"> <div style="border-bottom: 1px solid black; width: 45%; text-align: center;">(Signature)</div> <div style="border-bottom: 1px solid black; width: 45%; text-align: center;">(Date)</div> </div>	Branch Mail Code : Phone Number : 214-665-2798 Fax Number :
Contracting Officer : Michael J. Pheeny Electronically Signed by Michael J. Pheeny 07/11/2016 <div style="display: flex; justify-content: space-between; margin-top: 10px;"> <div style="border-bottom: 1px solid black; width: 45%; text-align: center;">(Signature)</div> <div style="border-bottom: 1px solid black; width: 45%; text-align: center;">(Date)</div> </div>	Branch Mail Code : Phone Number : 214-665-2798 Fax Number :
Other Agency Official <div style="display: flex; justify-content: space-between; margin-top: 10px;"> <div style="border-bottom: 1px solid black; width: 45%; text-align: center;">(Signature)</div> <div style="border-bottom: 1px solid black; width: 45%; text-align: center;">(Date)</div> </div>	Branch Mail Code : Phone Number : Fax Number :

Specific Elements: Analyze -Data that has been collected.,Collect -Samples ,Document -The removal activities. Prepare a written report.,Support -The removal activities,Advise -The OSC on disposal options and completion of the removal activities.
Description of Work: The initial TDD funding ceiling is set at \$12,000.

Document conditions and conduct air monitoring at the site of the derailment and surrounding areas.

The Contractors shall conduct air monitoring activities at the Site and surrounding areas as directed by the OSC. The Contractors shall document conditions at the Site through photographs and logbook. The Contractor shall assist the OSC in the compilation of any data collected and in the management of said data in Scribe, OSC.net or any other formats as directed. The Contractor shall issue an Acknowledgement of Completion Report summarizing the details of the response in a format as determined by the OSC.

U.S. EPA, Region 6
1445 Ross Avenue, Suite 1200
Dallas, TX 75202-2733
Vendor : WESTON SOLUTIONS, INC.

TDD # : 1/WESTON-042-16-023
Amendment # : 001
Contract # : EP-W-06-042

TDD Title :BNSF Panhandle Derailment
Purpose :EXTEND POP

Priority :HIGH
Overtime Authorized : Yes
Invoice Unit :

Verbal Date : 06/28/2016
Start Date : 06/28/2016
Completion Date : 10/15/2016
Effective Date : 06/28/2016

SSID : A6NJ
Project/Site Name : BNSF Panhandle Derailment
Project Address :City of Panhandle
County : Carson
City : Panhandle
State : TX
Zip Code : 79068

Work Area : Response / Removal
Work Area Code : RS
Activity : Fund Lead Removal
Activity Code : RV
Operable Unit :
Emergency Code :
FPN :
Performance Based : No

Authorized TDD Ceiling :	Amount	LOE (Hours)
Previous Action(s) :	\$12,000.00	0.00
This Action :	\$0.00	0.00
New Total :	\$12,000.00	0.00

Specific Elements :
See Schedule

Description of Work :
See Schedule

Region Specific :
CERCLIS :

Misc 2 :

Accounting and Appropriation Information:										SFO:
Line	Budget / FY	Approp	Budget	Program Element	Object Class	Site Project	Cost Org	DCN Line-ID	Funding Category	TDD Amount

--

U.S. EPA, Region 6
1445 Ross Avenue, Suite 1200
Dallas, TX 75202-2733

Vendor: WESTON SOLUTIONS, INC.

TDD #: 1/WESTON-042-16-023

Amendment #: 001

Contract #: EP-W-06-042

Project Officer : Will LaBombard <div style="display: flex; justify-content: space-between;"> <div>_____</div> <div>_____</div> </div> <div style="display: flex; justify-content: space-between;"> <div>(Signature)</div> <div>(Date)</div> </div>	Branch Mail Code: Phone Number : 214-665-7199 Fax Number :
Contracting Officer Representative William Rhotenberry <div style="display: flex; justify-content: space-between;"> <div>_____</div> <div>_____</div> </div> <div style="display: flex; justify-content: space-between;"> <div>(Signature)</div> <div>(Date)</div> </div>	Branch Mail Code : Phone Number : 214-665-8372 Fax Number :
Contract Specialist: Michael J. Pheeny <div style="display: flex; justify-content: space-between;"> <div>_____</div> <div>_____</div> </div> <div style="display: flex; justify-content: space-between;"> <div>(Signature)</div> <div>(Date)</div> </div>	Branch Mail Code : Phone Number : 214-665-2798 Fax Number :
Contracting Officer : Michael J. Pheeny Electronically Signed by Michael J. Pheeny 07/21/2016 <div style="display: flex; justify-content: space-between;"> <div>_____</div> <div>_____</div> </div> <div style="display: flex; justify-content: space-between;"> <div>(Signature)</div> <div>(Date)</div> </div>	Branch Mail Code : Phone Number : 214-665-2798 Fax Number :
Other Agency Official <div style="display: flex; justify-content: space-between;"> <div>_____</div> <div>_____</div> </div> <div style="display: flex; justify-content: space-between;"> <div>(Signature)</div> <div>(Date)</div> </div>	Branch Mail Code : Phone Number : Fax Number :

Specific Elements:

Base ORIG - Analyze -Data that has been collected.,Collect -Samples ,Document -The removal activities. Prepare a written report.,Support -The removal activities,Advise -The OSC on disposal options and completion of the removal activities.

Description of Work:

Amendment 001 - This amendment is to extend the POP to 10/15/2016. No additional funding is required.

Base ORIG - The initial TDD funding ceiling is set at \$12,000.

Document conditions and conduct air monitoring at the site of the derailment and surrounding areas.

The Contractors shall conduct air monitoring activities at the Site and surrounding areas as directed by the OSC. The Contractors shall document conditions at the Site through photographs and logbook. The Contractor shall assist the OSC in the compilation of any data collected and in the management of said data in Scribe, OSC.net or any other formats as directed. The Contractor shall issue an Acknowledgement of Completion Report summarizing the details of the response in a format as determined by the OSC.